

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,174,277 B2
APPLICATION NO. : 10/601208
DATED : February 6, 2007
INVENTOR(S) : Curtis A. Vock et al.


Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 15, line 27, "FIG. 110;" should read --FIG. 10;--;
Column 22, line 26, "about 12 second" should read --about 1/2 second--;
Column 28, line 43, "the MMD)" should read --the MMD--;
Column 32, line 2, "FIG. 1" should read --FIG. 11--; line 34, "FIG. 1" should read --FIG. 11--;
Column 33, line 58, "<Sync><Sensor ID>" should read --<Sync> <Sensor ID>--;
Column 34, line 5, "airtime is transmitted" should read --airtime is retransmitted--;
Column 55, line 59, "/1.2" should read --1/2--;
Column 66, line 47, "identical smart" should read --identical smart sensors--; line 49, "identical smart" should read --identical smart sensors--;

Signed and Sealed this

Third Day of July, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office